2018 - San Diego, CA	Andaz San Diego	Bristol Hotel	Courtyard by Marriott SD Downtown	Embassy Suites SD Bay Downtown
Hotel Accessibility Survey	600 F Street	1055 1st Ave	530 Broadway	601 Pacific Highway
Parking/Hotel Entrance			· ·	<u> </u>
Accessible overnight parking in garage or adjacent to hotel:	YES	YES	YES	YES
V. 1	Valet: \$49	Valet: \$32	Valet: \$47	Valet: \$50
If valet parking is available, daily rate? If self parking, daily rate?	Self: N/A	Self: N/A	Self: N/A	Self: N/A
Hotel garage accommodates raised roof accessible vans:	NO	N/A	YES	YES
Curb cuts leading from valet parking area to main entrance:	N/A	YES	YES	YES
Curb cuts at passenger drop off area:	NO	YES	YES	YES
Accessible on street parking in front of hotel:	NO	NO	YES	NO
Total main entrances to the hotel:	1	1	2	2
Is the main entrance fully accessible (i.e., no stairs or barriers)?	YES	YES	YES	YES
Doors at main entrance open without too much force:	YES	YES	YES	YES
Main entrance equipped with power doors:	NO	NO	YES	YES
If there is a vestibule, there's adequate space for wheelchair:	YES	YES	YES	YES
Single-door entrances at least a minimum of 32" wide and double-door entrances at least a	1125	123	123	11.5
minimum of 48" wide	YES	YES	YES	YES
Public Areas				
Accessible entrance provides direct access to main lobby & elevators:	YES	YES	YES	YES
Registration desk accessible to wheelchair user:	YES	YES	YES	YES
Phones equipped with text telephone TT or TDD:	NO NO	YES	YES	YES
Accessible drinking fountain for wheelchair user:	NO NO	N/A	YES	NO
Accessible utiliking fountain for wheelchair user.	3: Rooftop, Lobby, Meeting	N/A	3: Lobby, Lower Level and	NO
Number of accessible public restrooms:			, ,	1: Lobby
Audible and viewal fire and among an automost	Spaces YES	YES	Mezzanine YES	YES
Audible and visual fire and emergency alarms:				
Signage inside the building is visible to wheelchair users:	YES	YES	YES	YES
Hallways and corridors have at least 36" cleanrance and space for turning and passing:	YES	YES	YES	YES
Doors into public spaces have at least 32" clear opening:	YES	YES	YES	YES
Fragrance free rooms: Meeting Rooms	YES	YES	YES	YES
Doors have at least 32" clear opening:	YES	YES	YES	YES
At least 18" clear wall space on pull side of the door, near handle:	YES	YSE	YES	YES
Door handles 48" high or less and operable with a closed fist:	YES	YES	YES	YES
·				
Is portable assistive listening system available, cost for usage?	NO NO	YES 2	NO 2	NO 1
Total floors with meeting rooms:	2			1
Meeting rooms or public areas not wheelchair accessible:	N/A	NONE	N/A	N/A
Temporary ramps available for use with raised podiums or head tables:	YES	YES	N/A	YES
Lighting in all meeting rooms non-glare, non-reflecting, and non-blinking:	NO	YES	YES	YES
Restaurants Number of food outlets / Postaurants are on property	1		2	1
Number of food outlets/Restaurants are on property:	1	A1 / A	2	1
Food outlets/restaurants accessible to people in wheelchairs:	YES	N/A	YES	YES
Are self-service counters no higher than 34"?	YES	N/A	YES	N/A
Restaurant staff trained to serve guests with disabilities and dietary constraints:	YES	N/A	YES	YES
Hotel Usability	\\	\;=0	1/20	1:50
Recreation areas/exercise facilities on accessible route of travel:	YES	YES	YES	YES
Accessible hotel business center:	YES	YES	YES	YES
Accessible pool area:	YES	N/A	N/A	YES
Pool equipped with a lift:	YES	N/A	N/A	YES
Changing rooms on accessible route of travel:	YES	N/A	YES	N/A
Accessible lockers in both men's and women's changing rooms:	N/A	N/A	N/A	N/A
Changing rooms have accessible roll-in shower with hand held shower:	N/A	N/A	N/A	N/A
There is a folding seat for the roll in showers:	N/A	YES	N/A	N/A
Elevators				
Visible and audible door opening/closing and floor indicators:	YES	YES	YES	YES
Raised or Braille lettering for elevator constrols and call button:	YES	YES	YES	YES
Accessible controls with raised or Braille lettering; at or below 48":	YES	YES	YES	YES

^{*}The information contained within this survey has been contributed by the specific venue listed. Although we have taken reasonable care to ensure its accuracy we accept no liability for any errors or omissions in the information.

2018 - San Diego, CA	Andaz San Diego	Bristol Hotel	Courtyard by Marriott SD Downtown	Embassy Suites SD Bay Downtown
Hotel Accessibility Survey	600 F Street	1055 1st Ave	530 Broadway	601 Pacific Highway
Accessible Guest Rooms				
otal guest rooms on property:	159	114	245	341
otal wheelchair accessible rooms:	9	7	13	11
ccessible rooms with roll in showers:	9	2	4	4
dequate space for roll-away beds:	N/A	YES	NO	YES, Kings Only
Bed options for accessible rooms:			ALL	Kings Only
Doors have "Lever" hardware:	N/A	YES	YES	YES
ccessible rooms have at least 32" clear opening:	YES	YES	YES	YES
Ooor locks & keys are easily operable by one hand:	YES	YSE	YES	YES
ecurity lock is easily operable and located within 48" of floor:	YES	N/A	YES	YES
Closet rods are within range of reach:	NO	YES	YES	YES
Drapery controls easily operable:	YES	YES	YES	YES
Vill hotel provide refrigerator if requested by guest?	YES	YES	YES	YES
ccessible light and temperature controls:	YES	YES	YES	YES
reepholes usable by people in wheelchairs or scooters:	NO	YES	YES	YES
rons and ironing boards located/mounted at lower heights:	YES	YES	YES	YES
owest floor with accessible rooms:	2nd floor	3rd Floor	2nd Floor	2nd Floor
Bathrooms in Wheelchair Accessible Guest Rooms				
Does the bathroom door open outward?	N/A	N/A	YES	YES
Doors at least 32" wide with at least 18" cleanrance on the pull side:	N/A	YES	YES	YES
Oors have "lever" hardware:	N/A	YES	YES	YES
hreshold of the door is less than 1/2" high:	N/A	N/A	YES	YES
Grab bars behind and on side wall Near the toilet:	YES	YES	YES	YES
oilet seat is 17" - 19" high:	YES	YES	YES	YES
Built in transfer seat provided at the tub:	N/A	YES	YES	YES
Portable tub seat available:	N/A	NO	YES	NO, already mounted
Grab bars provided on sidewall of the tub:	YES	YES	YES	YES
sink has 29" cleanrance below front apron; sink rim no higher than 34":	NO NO	YES	YES	YES
sink & shower faucets operable with a closed fist:	YES	YES	YES	YES
coap and other dispensers are accessible and usable with one closed fist:	NO NO	YES	YES	YES
Roll-showers are at least 36" x 60" :	YES	YES	YES	YES
Roll in shower with a folding seat:	NO NO	YES	YES	YES
Hand held shower with adjustable height bar:	YES	YES	YES	YES
Are shower controls operable with a closed fist?	YES	YES	YES	YES
owels and other amenities are within the accessible range of reach:	YES	YES	YES	YES
Guest Rooms For Hearing Impaired	1E3	TES	TES	1E3
lumber of in-house kits to be installed in guestrooms; cost?:	N/A	2, \$0	3, \$0	\$0
(its include notification devices for: door knocking?	N/A N/A	2, 30 YES	3, 30 YES	YES
Ÿ	·	YES	YES	YES
its include notification devices for telephone ringing? its include notification devices for alarm clock?	N/A N/A	YES	YES	YES
	· · · · · · · · · · · · · · · · · · ·	YES	YES	YES
ext telephones TT or TDD:	N/A			
Vs have closed captioning:	YES	YES	YES	YES
/isual emergency warning devices in all accessible rooms:	NO	YES	YES	YES
Usability of Standard Guest Rooms	NO	VEC	VEC	VEC
tandard rooms have a minimum 28" clear opening width:	NO N/A	YES	YES	YES
What is clear opening width of the bathroom door?	N/A	30" VES	1/50	32"
s the threshold of the doors less than 1/2" high?	NO NO	YES	YES	YES
ooms have grab bars on sidewall near toilet and on tub walls:	NO	N/A	YES	YES
dequate space between beds/furniture for wheelchair or scooter:	NO	==	YES	YES
accessible light and temperature controls:	YES	YES	YES	YES
accommodations for guests with chemical sensitivity:	NONE			Frangrance Free Rooms
Additional Notes	NONE			24 hour notice required for chemical sensitivity

^{*}The information contained within this survey has been contributed by the specific venue listed. Although we have taken reasonable care to ensure its accuracy we accept no liability for any errors or omissions in the information.

2018 - San Diego, CA	Hard Rock Hotel San Diego	Hilton San Diego Bayfront	Hilton San Diego Gaslamp Quarter	Hotel Indigo SD Gaslamp Quarter
Hotel Accessibility Survey	207 Fifth Ave	1 Park Boulevard	401 K Street	509 9th Ave
Parking/Hotel Entrance				
Accessible overnight parking in garage or adjacent to hotel:	YES	YES	YES	YES
If valet parking is available, daily rate? If self parking, daily rate?	Valet: \$49	Valet: \$50	Valet: \$49	Valet: \$47
in valet parking is available, daily rate: In sell parking, daily rate:	Self: N/A	Self: \$35	Self: N/A	Self: N/A
Hotel garage accommodates raised roof accessible vans:	NO	NO	NO	YES
Curb cuts leading from valet parking area to main entrance:	NO		YES	YES
Curb cuts at passenger drop off area:	NO		YES	NO
Accessible on street parking in front of hotel:	NO	NO	NO	YES
Total main entrances to the hotel:	3	3	3	2
Is the main entrance fully accessible (i.e., no stairs or barriers)?	YES	YES	YES	YES
Doors at main entrance open without too much force:	YES	YES	YES	YES
Main entrance equipped with power doors:	YES	YES	YES	YES
If there is a vestibule, there's adequate space for wheelchair:	YES	NO	YES	YES
Single-door entrances at least a minimum of 32" wide and double-door entrances at least a minimum	YES	N/A	YES	YES
of 48" wide	-	·	-	-
Public Areas	VEC	VEC	VEC	VEC
Accessible entrance provides direct access to main lobby & elevators:	YES YES	YES	YES YES	YES YES
Registration desk accessible to wheelchair user:				
Phones equipped with text telephone TT or TDD:	YES		YES	YES
Accessible drinking fountain for wheelchair user:	YES 4: 1st Floor, 2nd Floor and 4th		YES	YES
Number of accessible public restrooms:	4: 1st Floor, 2nd Floor and 4th Floor		2: Lobby, 2nd Floor	2: Lobby, Level 9
Audible and visual fire and emergency alarms:	YES	YES	YES	YES
Signage inside the building is visible to wheelchair users:	YES	YES	YES	YES
Hallways and corridors have at least 36" cleanrance and space for turning and passing:	YES		YES	YES
Doors into public spaces have at least 32" clear opening:	YES		YES	YES
Fragrance free rooms:	NO	YES	YES	YES
Meeting Rooms				
Doors have at least 32" clear opening:	YES		YES	YES
At least 18" clear wall space on pull side of the door, near handle:	YES			YES
Door handles 48" high or less and operable with a closed fist:	YES		YES	YES
Is portable assistive listening system available, cost for usage?	YES		YES	NO
Total floors with meeting rooms:	3		2	2
Meeting rooms or public areas not wheelchair accessible:	NONE		NONE	NONE
Temporary ramps available for use with raised podiums or head tables:	YES			NO
Lighting in all meeting rooms non-glare, non-reflecting, and non-blinking:	NO		YES	YES
Restaurants				
Number of food outlets/Restaurants are on property:	4	6	1	2
Food outlets/restaurants accessible to people in wheelchairs:	YES	YES	YES	YES
Are self-service counters no higher than 34"?	YES		N/A	YES
Restaurant staff trained to serve guests with disabilities and dietary constraints:	YES	YES	YES	YES
Hotel Usability				
Recreation areas/exercise facilities on accessible route of travel:	YES	YES	YES	YES
Accessible hotel business center:	YES	YES	YES	YES
Accessible pool area:	YES	YES	YES	N/A
Pool equipped with a lift:	YES	YES	YES	N/A
Changing rooms on accessible route of travel:	YES		YES	N/A
Accessible lockers in both men's and women's changing rooms:	YES		YES	N/A
Changing rooms have accessible roll-in shower with hand held shower:	YES		NO	N/A
There is a folding seat for the roll in showers:	YES		YES	YES
Elevators	VEC		VEC	VEC
Visible and audible door opening/closing and floor indicators:	YES	VFC	YES	YES
Raised or Braille lettering for elevator constrols and call button:	YES	YES	YES	YES
Accessible controls with raised or Braille lettering; at or below 48":	YES		YES	YES

^{*}The information contained within this survey has been contributed by the specific venue listed. Although we have taken reasonable care to ensure its accuracy we accept no liability for any errors or omissions in the information.

2018 - San Diego, CA	Hard Rock Hotel San Diego	Hilton San Diego Bayfront	Hilton San Diego Gaslamp Quarter	Hotel Indigo SD Gaslamp Quarter
Hotel Accessibility Survey	207 Fifth Ave	1 Park Boulevard	401 K Street	509 9th Ave
Accessible Guest Rooms				
Total guest rooms on property:	420	1190	286	210
Total wheelchair accessible rooms:	27	51		10
Accessible rooms with roll in showers:	27	11		10
Adequate space for roll-away beds:	YES	YES	YES	NO
Bed options for accessible rooms:	ALL	YES	YES	YES
Doors have "Lever" hardware:	YES		YES	YES
Accessible rooms have at least 32" clear opening:	YES		YES	YES
Door locks & keys are easily operable by one hand:	YES		YES	YES
Security lock is easily operable and located within 48" of floor:	YES		YES	YES
Closet rods are within range of reach:	YES		YES	YES
Drapery controls easily operable:	YES		YES	N/A
Will hotel provide refrigerator if requested by guest?	YES	YES	YES	YES
Accessible light and temperature controls:	YES	. = 2	YES	YES
Peepholes usable by people in wheelchairs or scooters:	YES		YES	YES
Irons and ironing boards located/mounted at lower heights:	YES		YES	YES
Lowest floor with accessible rooms:	3rd Floor	2nd Floor	2nd Floor	2nd Floor
Bathrooms in Wheelchair Accessible Guest Rooms	314 11661	2110 1 1001	2110 1 1001	2110 1 1001
Does the bathroom door open outward?	N/A		YES	YES
Doors at least 32" wide with at least 18" cleanrance on the pull side:	YES		YES	YES
Doors have "lever" hardware:	YES		YES	YES
Threshold of the door is less than 1/2" high:	NO NO		YES	YES
Grab bars behind and on side wall Near the toilet:	YES		YES	YES
Toilet seat is 17" - 19" high:	YES		YES	YES
Built in transfer seat provided at the tub:	YES		NO NO	YES
Portable tub seat available:	N/A		YES	YES
Grab bars provided on sidewall of the tub:	N/A N/A		YES	YES
Sink has 29" cleanrance below front apron; sink rim no higher than 34":	N/A N/A		YES	YES
Sink & shower faucets operable with a closed fist:	YES		YES	YES
Soap and other dispensers are accessible and usable with one closed fist:	YES		YES	N/A
Roll-showers are at least 36" x 60" :	YES		YES	YES
	YES		YES	YES
Roll in shower with a folding seat: Hand held shower with adjustable height bar:	YES		YES	YES
Are shower controls operable with a closed fist?	YES YES		YES YES	YES
Towels and other amenities are within the accessible range of reach:	YES		YES	YES
Guest Rooms For Hearing Impaired	2		47.60	10.00
Number of in-house kits to be installed in guestrooms; cost?:	2		17, \$0	10, \$0
Kits include notification devices for: door knocking?	YES		YES	YES
Kits include notification devices for telephone ringing?	YES		YES	YES
Kits include notification devices for alarm clock?	YES		YES	YES
Text telephones TT or TDD:	NO NEC		YES	YES
TVs have closed captioning:	YES		YES	YES
Visual emergency warning devices in all accessible rooms:	YES		YES	YES
Usability of Standard Guest Rooms	VEC		VE2	V50
Standard rooms have a minimum 28" clear opening width:	YES		YES	YES
What is clear opening width of the bathroom door?	39"		36"	
Is the threshold of the doors less than 1/2" high?	YES		YES	YES
Rooms have grab bars on sidewall near toilet and on tub walls:	NO			YES
Adequate space between beds/furniture for wheelchair or scooter:	YES		YES	YES
Accessible light and temperature controls:	YES			YES
Accommodations for guests with chemical sensitivity:			Chemical free cleaning	YES
Additional Notes				

^{*}The information contained within this survey has been contributed by the specific venue listed. Although we have taken reasonable care to ensure its accuracy we accept no liability for any errors or omissions in the information.

	Hotel Palomar San Diego	Hotel Z San Diego	Manchester Grand Hyatt San Diego	Marriott Marquis San Diego Marina
Hotel Accessibility Survey	1047 Fifth Ave	521 6th Ave	One Market Place	333 W Harbor Drive
Parking/Hotel Entrance				
ccessible overnight parking in garage or adjacent to hotel:	YES	NO	YES	YES
Contact and district and delicated and design and design and delicated a	Valet: \$49	Valet: \$45	Valet: \$49	Valet: \$50
valet parking is available, daily rate? If self parking, daily rate?	Self: N/A	Self: N/A	Self: \$35	Self: \$35
lotel garage accommodates raised roof accessible vans:	N/A	NO	NO	NO
curb cuts leading from valet parking area to main entrance:	YES	NO	YES	YES
Curb cuts at passenger drop off area:	YES	NO	YES	YES
ccessible on street parking in front of hotel:	N/A	YES	NO	YES
otal main entrances to the hotel:	2	1	4	Multiple
s the main entrance fully accessible (i.e., no stairs or barriers)?	YES	YES	YES	YES
oors at main entrance open without too much force:	YES	YES	YES	N/A
Main entrance equipped with power doors:	NO	YES	YES	YES
there is a vestibule, there's adequate space for wheelchair:	YES	N/A	YES	N/A
ingle-door entrances at least a minimum of 32" wide and double-door entrances at least a minimum	YES	YES	YES	YES
f 48" wide	-	-	-	-
Public Areas	VEC	VEC	VEC	VEC
Accessible entrance provides direct access to main lobby & elevators:	YES YES	YES YES	YES YES	YES YES
hones equipped with text telephone TT or TDD:	N/A	NO YES	YES	NO YES
ccessible drinking fountain for wheelchair user:	YES	NO NO	YES	YES
ccessible drinking fountain for wheelchair user.	TES	NO	153	3: Marina Kitchen, Grand
lumber of accessible public restrooms:	1: Mezzanine Level	1: 1st Floor	ALL	Ballroom and Presidio Room
audible and visual fire and emergency alarms:	YES	YES	YES	YES
ignage inside the building is visible to wheelchair users:	YES	YES	YES	YES
lallways and corridors have at least 36" cleanrance and space for turning and passing:	YES	YES	YES	YES
Doors into public spaces have at least 32" clear opening:	YES	YES	YES	YES
ragrance free rooms:	NO	YES	YES	N/A
Meeting Rooms				
Doors have at least 32" clear opening:	YES	N/A	YES	YES
t least 18" clear wall space on pull side of the door, near handle:	YES	N/A	YES	N/A
oor handles 48" high or less and operable with a closed fist:	YES	N/A	YES	YES
s portable assistive listening system available, cost for usage?	N/A	N/A		YES
otal floors with meeting rooms:	1	N/A	6	4
Meeting rooms or public areas not wheelchair accessible:	N/A	N/A	NONE	N/A
emporary ramps available for use with raised podiums or head tables:	N/A	N/A	YES	YES
ighting in all meeting rooms non-glare, non-reflecting, and non-blinking:	N/A	N/A	YES	YES
Restaurants				
lumber of food outlets/Restaurants are on property:	1	0	7	5
ood outlets/restaurants accessible to people in wheelchairs:	YES	N/A	YES	YES
are self-service counters no higher than 34"?	YES	N/A	YES	N/A
estaurant staff trained to serve guests with disabilities and dietary constraints:	YES	N/A	YES	YES
Hotel Usability	VEC	N1/A	VEC	VEC
decreation areas/exercise facilities on accessible route of travel:	YES	N/A	YES YES	YES
Accessible notel business center:	N/A YES	N/A N/A	YES	YES YES
ool equipped with a lift:	YES	N/A N/A	YES	YES
changing rooms on accessible route of travel:	YES	N/A N/A	YES	YES
ccessible lockers in both men's and women's changing rooms:	YES	N/A N/A	NO NO	YES
changing rooms have accessible roll-in shower with hand held shower:	N/A	N/A	YES	N/A
here is a folding seat for the roll in showers:	YES	N/A N/A	YES	YES
Elevators	1.23	N/A	125	125
risible and audible door opening/closing and floor indicators:	YES	YES	NO	YES
aised or Braille lettering for elevator constrols and call button:	YES	NO	YES	YES
aiseu of dianie letternik for elevator constrois and tall dutton.		.,,		YES

^{*}The information contained within this survey has been contributed by the specific venue listed. Although we have taken reasonable care to ensure its accuracy we accept no liability for any errors or omissions in the information.

2018 - San Diego, CA	Hotel Palomar San Diego	Hotel Z San Diego	Manchester Grand Hyatt San Diego	Marriott Marquis San Diego Marina
Hotel Accessibility Survey	1047 Fifth Ave	521 6th Ave	One Market Place	333 W Harbor Drive
Accessible Guest Rooms				
Total guest rooms on property:	211	96	1628	1360
Total wheelchair accessible rooms:	7	5	40	39
Accessible rooms with roll in showers:	2	1	16	16
Adequate space for roll-away beds:	N/A	NO	YES	YES
Bed options for accessible rooms:	King Only	YES	YES	YES
Doors have "Lever" hardware:	YES	NO	YES	YES
Accessible rooms have at least 32" clear opening:	YES	YES	YES	YES
Door locks & keys are easily operable by one hand:	YES	YES	YES	N/A
Security lock is easily operable and located within 48" of floor:	YES	YES	YES	YES
Closet rods are within range of reach:	YES	YES		YES
Drapery controls easily operable:	YES	YES	YES	YES
Will hotel provide refrigerator if requested by guest?	YES	YES	YES	YES
Accessible light and temperature controls:	YES	YES	YES	YES
Peepholes usable by people in wheelchairs or scooters:	YES	YES	YES	YES
Irons and ironing boards located/mounted at lower heights:	YES	N/A	YES	YES
Lowest floor with accessible rooms:		Ground	5th Floor	4th Floor
Bathrooms in Wheelchair Accessible Guest Rooms		o.ca.ia		
Does the bathroom door open outward?	YES	NO	YES	N/A
Doors at least 32" wide with at least 18" cleanrance on the pull side:	YES	YES	YES	YES
Doors have "lever" hardware:	YES	N/A	123	N/A
Threshold of the door is less than 1/2" high:	YES	NO	YES	N/A
Grab bars behind and on side wall Near the toilet:	YES	YES	YES	YES
Toilet seat is 17" - 19" high:	YES	YES	YES	YES
Built in transfer seat provided at the tub:	YES	YES	NO NO	YES
Portable tub seat available:	YES	YES	YES	YES
Grab bars provided on sidewall of the tub:	YES	YES	YES	YES
Sink has 29" cleanrance below front apron; sink rim no higher than 34":	YES	YES	YES	YES
Sink & shower faucets operable with a closed fist:	YES	YES	YES	YES
Soap and other dispensers are accessible and usable with one closed fist:	YES	YES	YES	N/A
Roll-showers are at least 36" x 60":	YES	YES	11.3	YES
Roll in shower with a folding seat:	YES	YES	YES	YES
Hand held shower with adjustable height bar:	YES	YES	YES	YES
Are shower controls operable with a closed fist?	YES	YES	YES	YES
·	YES	YES		
Towels and other amenities are within the accessible range of reach:	YES	YES	YES	YES
Guest Rooms For Hearing Impaired Number of in-house kits to be installed in guestrooms; cost?:	N/A			24 60
	N/A YES	VEC	YES	24, \$0
Kits include notification devices for: door knocking?	YES	YES YES	TES	YES
Kits include notification devices for telephone ringing? Kits include notification devices for alarm clock?			NO	NO NO
	YES	N/A	NO	NO NO
Text telephones TT or TDD:	YES	NO NO	VE0	NO NES
TVs have closed captioning:	YES	YES	YES	YES
Visual emergency warning devices in all accessible rooms:	YES	YES	YES	YES
Usability of Standard Guest Rooms	NEG.	1/50	7/50	1/50
Standard rooms have a minimum 28" clear opening width:	YES	YES	YES	YES
What is clear opening width of the bathroom door?	N/A			35"
Is the threshold of the doors less than 1/2" high?	YES	YES	YES	YES
Rooms have grab bars on sidewall near toilet and on tub walls:	YES	NO	NO	NO
Adequate space between beds/furniture for wheelchair or scooter:	YES	NO	YES	YES
Accessible light and temperature controls:	YES	NO	YES	YES
Accommodations for guests with chemical sensitivity:	YES	YES	Allergen, frangrance free room upon request	Fragrant free rooms upon request
Additional Notes				

^{*}The information contained within this survey has been contributed by the specific venue listed. Although we have taken reasonable care to ensure its accuracy we accept no liability for any errors or omissions in the information.

2018 - San Diego, CA	Omni San Diego Hotel	The US Grant Hotel	Westgate Hotel	Westin San Diego Gaslamp Quarter
Hotel Accessibility Survey	675 L Street	326 Broadway	1055 2nd Ave	910 Broadway Circle
Parking/Hotel Entrance		· ·		· ·
Accessible overnight parking in garage or adjacent to hotel:	N/A	YES	YES	N/A
If you have not the control of the c	Valet: \$50	Valet: \$49	Valet: \$40	Valet: \$50
If valet parking is available, daily rate? If self parking, daily rate?	Self: N/A	Self: N/A	Self: N/A	Self: N/A
Hotel garage accommodates raised roof accessible vans:	NO	NO	YES	NO
Curb cuts leading from valet parking area to main entrance:	YES	YES	YES	YES
Curb cuts at passenger drop off area:	YES	N/A	YES	YES
Accessible on street parking in front of hotel:	N/A	N/A	NO	NO
Total main entrances to the hotel:	3	3	2	1
Is the main entrance fully accessible (i.e., no stairs or barriers)?	YES	YES	YES	YES
Doors at main entrance open without too much force:	YES	YES	YES	YES
Main entrance equipped with power doors:	YES	YES	NO	YES
If there is a vestibule, there's adequate space for wheelchair:	YES	N/A	N/A	YES
Single-door entrances at least a minimum of 32" wide and double-door entrances at least a minimum	YES	N/A	YES	YES
of 48" wide	5	,		
Public Areas	VES	VEC) /= 0	1,50
Accessible entrance provides direct access to main lobby & elevators:	YES	YES	YES	YES
Registration desk accessible to wheelchair user:	YES	YES	YES	YES
Phones equipped with text telephone TT or TDD:	YES	NO	NO NO	YES
Accessible drinking fountain for wheelchair user:	YES	N/A	N/A	NO
Number of accessible public restrooms:	5: Lobby, 4th, 5th, 6th Floors	5: Lower Level, Lobby, 2nd Floor, Mezzanine	9	6: 2nd, 3rd, 4th Floors
Audible and visual fire and emergency alarms:	YES	YES	YES	YES
Signage inside the building is visible to wheelchair users:	YES	YES	YES	YES
Hallways and corridors have at least 36" cleanrance and space for turning and passing:	YES	YES	YES	YES
Doors into public spaces have at least 32" clear opening:	YES	YES	YES	YES
Fragrance free rooms:	YES	YES	YES	YES
Meeting Rooms				
Doors have at least 32" clear opening:	YES	YES	YES	YES
At least 18" clear wall space on pull side of the door, near handle:	YES	YES	YES	YES
Door handles 48" high or less and operable with a closed fist:	YES	YES	YES	YES
Is portable assistive listening system available, cost for usage?	NO	NO	YES	
Total floors with meeting rooms:	5	3	3	4
Meeting rooms or public areas not wheelchair accessible:	N/A	NONE	NONE	N/A
Temporary ramps available for use with raised podiums or head tables:	YES	YES	YES	YES
Lighting in all meeting rooms non-glare, non-reflecting, and non-blinking:	YES	YES	YES	YES
Restaurants				
Number of food outlets/Restaurants are on property:	2	1	2	1
Food outlets/restaurants accessible to people in wheelchairs:	YES	YES	YES	YES
Are self-service counters no higher than 34"?	YES	N/A	YES	NO
Restaurant staff trained to serve guests with disabilities and dietary constraints:	YES	YES	YES	YES
Hotel Usability				
Recreation areas/exercise facilities on accessible route of travel:	YES	YES	YES	YES
Accessible hotel business center:	YES	N/A	YES	YES
Accessible pool area:	YES	N/A	YES	YES
Pool equipped with a lift:	YES	N/A	YES	YES
Changing rooms on accessible route of travel:	YES	N/A	YES	YES
Accessible lockers in both men's and women's changing rooms:	NO	N/A	YES	YES
Changing rooms have accessible roll-in shower with hand held shower:	YES	N/A	YES	YES
There is a folding seat for the roll in showers:	YES	NO	YES	YES
Elevators	NE -	105		
Visible and audible door opening/closing and floor indicators:	YES	YES	N/A	YES
Raised or Braille lettering for elevator constrols and call button:	YES	YES	N/A	YES
Accessible controls with raised or Braille lettering; at or below 48":	YES	YES	YES	YES

^{*}The information contained within this survey has been contributed by the specific venue listed. Although we have taken reasonable care to ensure its accuracy we accept no liability for any errors or omissions in the information.

2018 - San Diego, CA	Omni San Diego Hotel	The US Grant Hotel	Westgate Hotel	Westin San Diego Gaslamp Quarter
Hotel Accessibility Survey	675 L Street	326 Broadway	1055 2nd Ave	910 Broadway Circle
Accessible Guest Rooms				
Total guest rooms on property:	511	270	223	450
Total wheelchair accessible rooms:	17	12	7	21
Accessible rooms with roll in showers:	7	5	2	4
Adequate space for roll-away beds:	YES	YES	YES	In 9 only
Bed options for accessible rooms:	YES	YES	Double/Double	YES
Doors have "Lever" hardware:	YES	YES	NO	YES
Accessible rooms have at least 32" clear opening:	YES	YES	YES	YES
Door locks & keys are easily operable by one hand:	YES	YES	YES	YES
Security lock is easily operable and located within 48" of floor:	YES	YES	YES	YES
Closet rods are within range of reach:	YES	YES	YES	YES
Drapery controls easily operable:	YES	YES	YES	YES
Will hotel provide refrigerator if requested by guest?	YES	YES	YES	YES
Accessible light and temperature controls:	YES	YES	YES	YES
Peepholes usable by people in wheelchairs or scooters:	YES	YES	YES	YES
Irons and ironing boards located/mounted at lower heights:	YES	YES	YES	YES
Lowest floor with accessible rooms:	6th	3rd Floor	4th Floor	4th Floor
Bathrooms in Wheelchair Accessible Guest Rooms				
Does the bathroom door open outward?	YES	YES	YES	N/A
Doors at least 32" wide with at least 18" cleanrance on the pull side:	YES	YES	YES	YES
Doors have "lever" hardware:	YES	YES	YES	YES
Threshold of the door is less than 1/2" high:	YES	YES	NO	YES
Grab bars behind and on side wall Near the toilet:	YES	YES	YES	YES
Toilet seat is 17" - 19" high:	YES	YES	YES	YES
Built in transfer seat provided at the tub:	NO	NO	YES	NO
Portable tub seat available:	YES	YES	YES	YES
Grab bars provided on sidewall of the tub:	YES	YES	YES	NO
Sink has 29" cleanrance below front apron; sink rim no higher than 34":	YES	YES	YES	YES
Sink & shower faucets operable with a closed fist:	NO	YES	NO NO	YES
Soap and other dispensers are accessible and usable with one closed fist:	YES	N/A	YES	YES
Roll-showers are at least 36" x 60":	YES	YES	YES	YES
Roll in shower with a folding seat:	YES	NO	YES	YES
Hand held shower with adjustable height bar:	YES	YES	YES	YES
Are shower controls operable with a closed fist?	YES	YES	YES	YES
Towels and other amenities are within the accessible range of reach:	YES	YES	YES	YES
Guest Rooms For Hearing Impaired	1E3	153	TE3	1E3
Number of in-house kits to be installed in guestrooms; cost?:	5, \$0	N/A	N/A	3, \$0
Kits include notification devices for: door knocking?	7, 50 YES	N/A	N/A	YES
Kits include notification devices for telephone ringing?	YES	N/A	N/A	YES
Kits include notification devices for telephone ringing? Kits include notification devices for alarm clock?	NO NO	N/A	N/A	YES
Text telephones TT or TDD:	YES	N/A N/A	N/A	YES
	YES	YES	YES	YES
TVs have closed captioning:	YES	YES	YES	YES
Visual emergency warning devices in all accessible rooms:	YES	, AE2	AE2	YES
Usability of Standard Guest Rooms	VEC	VEC	VEC	VEC
Standard rooms have a minimum 28" clear opening width: What is clear opening width of the bathroom door?	YES	YES	YES	YES
	VEC	32"	VEC	28"
Is the threshold of the doors less than 1/2" high?	YES	YES	YES	YES
Rooms have grab bars on sidewall near toilet and on tub walls:	YES	NO NO	NO	NO
Adequate space between beds/furniture for wheelchair or scooter:	YES	NO	YES	NO NO
Accessible light and temperature controls:	YES	YES	YES	NO
Accommodations for guests with chemical sensitivity:	Can adjust cleaning prior to and during arrival	Advanced notice required	Hyperallergenic options	Fragrance Free Rooms
Additional Notes				

^{*}The information contained within this survey has been contributed by the specific venue listed. Although we have taken reasonable care to ensure its accuracy we accept no liability for any errors or omissions in the information.

2018 - San Diego, CA	Wyndham San Diego Bayside
Hotel Accessibility Survey	1355 North Harbor Dr
Parking/Hotel Entrance	
Accessible overnight parking in garage or adjacent to hotel:	YES
If you at your is a visible and it yes a life of the your in a state of the year.	Valet: \$40
If valet parking is available, daily rate? If self parking, daily rate?	Self: \$29
Hotel garage accommodates raised roof accessible vans:	NO
Curb cuts leading from valet parking area to main entrance:	YES
Curb cuts at passenger drop off area:	YES
Accessible on street parking in front of hotel:	YES
Total main entrances to the hotel:	2
Is the main entrance fully accessible (i.e., no stairs or barriers)?	YES
Doors at main entrance open without too much force:	YES
Main entrance equipped with power doors:	YES
If there is a vestibule, there's adequate space for wheelchair:	YES
Single-door entrances at least a minimum of 32" wide and double-door entrances at least a minimum	123
of 48" wide	YES
Public Areas	
Accessible entrance provides direct access to main lobby & elevators:	YES
Registration desk accessible to wheelchair user:	YES
Phones equipped with text telephone TT or TDD:	NO
Accessible drinking fountain for wheelchair user:	NO
Accessible driffking fourtain for wheelchair user.	NO
Number of accessible public restrooms:	
Audible and visual fire and emergency alarms:	YES
Signage inside the building is visible to wheelchair users:	YES
Hallways and corridors have at least 36" cleanrance and space for turning and passing:	YES
Doors into public spaces have at least 32" clear opening:	YES
Fragrance free rooms:	YES
Meeting Rooms	
Doors have at least 32" clear opening:	YES
At least 18" clear wall space on pull side of the door, near handle:	YES
Door handles 48" high or less and operable with a closed fist:	YES
Is portable assistive listening system available, cost for usage?	YES
Total floors with meeting rooms:	2
Meeting rooms or public areas not wheelchair accessible:	N/A
Temporary ramps available for use with raised podiums or head tables:	YES
Lighting in all meeting rooms non-glare, non-reflecting, and non-blinking:	YES
Restaurants	
Number of food outlets/Restaurants are on property:	3
Food outlets/restaurants accessible to people in wheelchairs:	YES
Are self-service counters no higher than 34"?	N/A
Restaurant staff trained to serve guests with disabilities and dietary constraints:	YES
Hotel Usability	1123
Recreation areas/exercise facilities on accessible route of travel:	YES
Accessible hotel business center:	VEC
Accessible pool area:	YES VES
Pool equipped with a lift:	YES
Pool equipped with a lift: Changing rooms on accessible route of travel:	YES
	N/A
Accessible lockers in both men's and women's changing rooms:	N/A
Changing rooms have accessible roll-in shower with hand held shower:	N/A
There is a folding seat for the roll in showers:	N/A
Elevators	V=-
Visible and audible door opening/closing and floor indicators:	YES
Raised or Braille lettering for elevator constrols and call button:	YES
Accessible controls with raised or Braille lettering; at or below 48":	YES

2018 - San Diego, CA	Wyndham San Diego Bayside
Hotel Accessibility Survey	1355 North Harbor Dr
Accessible Guest Rooms	
Total guest rooms on property:	600
Total wheelchair accessible rooms:	ALL
Accessible rooms with roll in showers:	3
Adequate space for roll-away beds:	YES
Bed options for accessible rooms:	YES
Doors have "Lever" hardware:	YES
Accessible rooms have at least 32" clear opening:	YES
Door locks & keys are easily operable by one hand:	YES
Security lock is easily operable and located within 48" of floor:	YES
Closet rods are within range of reach:	YES
Drapery controls easily operable:	YES
Will hotel provide refrigerator if requested by guest?	YES
Accessible light and temperature controls:	YES
Peepholes usable by people in wheelchairs or scooters:	YES
Irons and ironing boards located/mounted at lower heights:	YES
Lowest floor with accessible rooms:	1st Floor
Bathrooms in Wheelchair Accessible Guest Rooms	
Does the bathroom door open outward?	N/A
Doors at least 32" wide with at least 18" cleanrance on the pull side:	YES
Doors have "lever" hardware:	YES
Threshold of the door is less than 1/2" high:	N/A
Grab bars behind and on side wall Near the toilet:	YES
Toilet seat is 17" - 19" high:	YES
Built in transfer seat provided at the tub:	NO
Portable tub seat available:	YES
Grab bars provided on sidewall of the tub:	YES
Sink has 29" cleanrance below front apron; sink rim no higher than 34":	YES
Sink & shower faucets operable with a closed fist:	YES
Soap and other dispensers are accessible and usable with one closed fist:	N/A
Roll-showers are at least 36" x 60" :	YES
Roll in shower with a folding seat:	NO
Hand held shower with adjustable height bar:	YES
Are shower controls operable with a closed fist?	YES
Towels and other amenities are within the accessible range of reach:	YES
Guest Rooms For Hearing Impaired	
Number of in-house kits to be installed in guestrooms; cost?:	
Kits include notification devices for: door knocking?	YES
Kits include notification devices for telephone ringing?	YES
Kits include notification devices for alarm clock?	YES
Text telephones TT or TDD:	YES
TVs have closed captioning:	YS
Visual emergency warning devices in all accessible rooms:	NO
Usability of Standard Guest Rooms	VES
Standard rooms have a minimum 28" clear opening width:	YES
What is clear opening width of the bathroom door?	VEC
Is the threshold of the doors less than 1/2" high?	YES
Rooms have grab bars on sidewall near toilet and on tub walls:	YES
Adequate space between beds/furniture for wheelchair or scooter:	YES
Accessible light and temperature controls:	YES
Accommodations for guests with chemical sensitivity:	
Additional Notes	